

Alpha 9500 – Version 3.03 Firmware Notes

1. The Autotune algorithm in the amplifier has been further refined.

2. Two more protection faults have been added:

Fault 20 - AC Input Voltage out of range for AC tap setting

Fault 21 - Cathode bias (+40vdc) did not come up